

1. Place the glass on the socket, then secured by metal cap and socket ring
2. The another 1PC as same the step 1

